

Testing laboratory for climatic, mechanical, and corrosive environmental test

QUALITY TEST CERTIFICATE

Test report No. 20-15685 Rev.01

Client	Knick Elektronische Messgeräte GmbH & Co. KG Beuckestraße 22 14163 Berlin	
Equipment under test	Protos II quantity labelled No.	4400C 1 sample 22675000
Purpose	Test for the certification of the corrosive resistance according to specifications of the standards and to the demands of the client. The test was carried out in the test laboratory TZO Technologie-Zentrum für Oberflächentechnik und Umweltschutz Leipzig GmbH.	
Test program	Harmful gas test - Test Ke, method 4	according to IEC 60068-2-60
Test period	3 July to 13 July 2020	
Execution /results	see page 2 to 3	
Total number of pages	9 (incl. 2 appendices)	
Test results	The test was carried out according to the specifications	

The test was carried out according to the specifications of the standards and to the demands of the client. During and after the test no damage or malfunctions were determined at the specimen.

Passed - according to the client, the measured values determined during the test were within the prescribed limits.

Ch Unebol

Dipl.-Ing. (FH) Ch. Kretschmer Head of the testing laboratory Berlin, 08 October 2020





Sitz der Gesellschaft: Berlin Amtsgericht Berlin Charlottenburg HRB 38393 USt.-ID-Nr. DE 137 190 620

Geschäftsführer: Dipl.-Ing. Bernd Rhiemeier Berliner Volksbank eG BIC BEVODEBB IBAN DE56 1009 0000 8301 8410 28 Commerzbank AG BIC DRESDEFF100 IBAN DE53 1008 0000 0400 4292 00



Dipl.-Ing.M. Geburtig Test engineer



Test report-No. 20-15685 Rev.01 page 2 / 3

1 <u>Purpose</u>

Test for the certification of the corrosive resistance according to the specifications of the standards and to the demands of the client.

2 Equipment under test

Protos II

4400C

with following modules:	 digital module MS4400-160 (inside the device housing) storage card F-ZU1080-P-N-D (inside the device housing) conductivity sensor F-SE604-MS (outside the test chamber)
Power supply	24 V _{DC}
dimensions / weight	appr. 165 x 160 x 22 mm, appr. 4 kg
quantity	1 sample
labelled No.	22675000

3 Basics

3.1 Demands of the client

3.2 Used standards

 IEC 60068-1:2013
 DIN EN 60068-1; VDE 0468-1:2015-09

 "Environmental testing - Part 1: General and guidance"

IEC 60068-2-60:1995DIN EN 60068-2-60:1996-09"Environmental testing - Part 2-60: Tests - Test Ke: Flowing mixed gas corrosion test"RemarkThis standard is not part of the Aucoteam GmbH accreditation!

4 Test program

Harmful gas test - Test Ke, method 4

according to the IEC 60068-2-60 and to the demands of the client

specimen		, supplied with 24 V _{DC} monitoring (by the client)
temperature	(23±5) °C	
humidity	(75±3) %	
gas concentration	SO ₂	0,2 ppm
	H_2S	0,01 ppm
	NO ₂	0,2 ppm
	Cl ₂	0,01 ppm
test duration	10 d	(240 h)

Visual inspection / functional check

Before and after the test, the specimen shall be examined for external damage and any other alterations.

During the test the displayed values will be checked visually every day.



Test report-No. 20-15685 Rev.01 page 3 / 3

5 <u>Realization</u>

Test for the certification of the corrosive resistance of the **Protos II** was carried out according to the test program, in compliance with the specifications of the current standards and according to the demands of the client in the test laboratory "TZO Technologie-Zentrum für Oberflächentechnik und Umweltschutz Leipzig GmbH", see appendix 2 – Test report 187/20 (13 July 2020).

Measuring and test equipment

corrosion test chamberK 350 (CTS GmbH)Flex Gas DetectorSPM (Honywell Analytics, Inc. USA)Power supply (24.0 VDC)TSX3510P (test laboratory TZO)

Visual inspection / functional check

After the test the specimen was examined for external damage and any other alterations. During the test the displayed values was checked visually every day.

6 <u>Results</u>

After the test of the Protos II 4400C with

- Harmful gas test - Test Ke, method 4 (10 d, operating)

- Test Ke

no damage or defects are visible, see appendix 2 – Test report 187/20 (13 July 2020), Before, during and after the test, the values displayed were within the plausible range; no significant deviations could be detected.

The further evaluation will be done by the client.

The test was carried out according to the specifications of the standards and to the demands of the client. During and after the test no damage or malfunctions were determined at the specimen.

Passed - according to the client, the measured values determined during the test were within the prescribed limits.

The results of the test refer exclusively to the above mentioned equipment under test. This report, or individual pages of this test report, may only be copied following the written consent of the testing laboratory. This test report No. 20-15685 Rev.01 includes 3 pages and 2 appendices.

Appendix 1 – Pictures (1 page)

Appendix 2 - Test report 187/20 (5 pages)

(TZO Technologie-Zentrum für Oberflächentechnik und Umweltschutz Leipzig GmbH 13 July 2020)

Changes in the Revision 01 compared to the Test report Pb 20-15685 of 15 July 2020:

- The evaluation of the measurement results by the customer was included as a test result.